




VACUUM PACKAGING MACHINE

MODEL 450A

(Model with New Vacuum Sensor)



OWNERS MANUAL

IMPORTANT SAFETY INSTRUCTIONS

SAVE THESE INSTRUCTIONS



This symbol points out important safety instructions which, if not followed, could endanger the personal safety and/or property of yourself and others. Read and follow all instructions in this manual before attempting to operate your machine.
Failure to comply with these instructions may result in personal injury.

General Operation

- Read, understand, and follow all instructions in the manual and on the machine before starting. Keep this manual in a safe place for further and regular reference and for ordering replacement parts.
- Only allow responsible individuals familiar with the instructions to operate the machine. Be sure to know controls and how to stop the machine quickly.
- Never put your hands near moving parts.
- Only allow qualified individuals for the maintenance of your machine.
- Remove all obstacles, which may interfere with the machine functions.
- Clear the work area such as electrical wires, buckets, knives etc.
- Be sure that everyone else is clear of your work area before operating the machine.
- Do not sit nor stand on the machine.
- Always turn off the machine after your work is done. Never leave a running machine unattended.
- Always disconnect and wait till the machine has cooled before attempting any maintenance.
- Do not wear loose fitting clothes or jewelry as they may get caught in moving parts of the machine.
- Always wear security shoes, to prevent injury caused by moving the machine or objects falling from the machine.
- Never exceed the time limit to seal, which is recommended by the manufacturer. This is to avoid any damage that may be caused to the sealing bars and to eliminate the risk of fire in the machine. Thus avoiding corporal burns.
- Never touch the sealing bars after they have been used, this will avoid corporal burns. Wait a few minutes to let the machine cool down before touching.
- Always make sure that the sealing bars are well installed in their "Guide Blocks" before starting a cycle.
- Never incline the machine more than 30 degrees, it may tip over and hurt someone seriously.
- Work only in daylight or good artificial light.

Do not operate the machine while under the influence of alcohol or drugs!

Service

- Use proper containers when draining the oil. Do not use food or beverage containers that may mislead someone into drinking from them. Properly dispose of the containers, or store in a safe place immediately following the draining of the oil.
- Prior to disposal, determine the proper method to dispose of waste from your local office of Environmental Protection Agency. Recycling centers are established to properly dispose of materials in an environmentally safe fashion.

Do not pour oil or other fluids into the ground, down a drain or into a body of water.



Warning-Your responsibility:

This machine should only be operated by personal who can read, understand and respect warnings and instructions regarding this machine in the owners manual. Save these instructions for future reference.

VACUUM PACKAGING MACHINE

MODEL 450A

(MC-40 SIPROMAC)

GENERAL TABLE OF CONTENTS

I OPERATION INSTRUCTIONS

II MECHANICAL

- A- 450A Front view assembly drawing
- B- 450A Rear view assembly drawing
- C- P.C. board support drawing
- D- 450A Structure assembly drawing
- E- Seal bar assembly drawings (twin seal)
- F- Seal bar assembly drawings (electrical bag cut option)
- G- Cover assembly drawings
- H- Gas injection kit installation drawing
(gas injection option)

III ELECTRICAL

- A- Electrical drawings

IV PNEUMATIC

- A- Pneumatic drawing

VACUUM PACKAGING MACHINES-OPERATION INSTRUCTIONS

TABLE OF CONTENTS

1. Setting up the machine
2. Electrical connection
3. Operation
 - 3.1 Working principles
 - 3.2 Special packaging
 - 3.2.1 Gas flushing
 - 3.2.2 Electrical bag cut (optional)
 - 3.3 Vacuum packaging operation
 - 3.3.1 Basics
 - 3.3.2 Functions menu
 - 3.3.2.1 Create a program
 - 3.3.2.2 Delete a program
 - 3.3.2.3 Select operating mode
 - 3.3.3 Programs menu
 - 3.3.3.1 Program identification
 - 3.3.3.2 Vacuum time setting (sensor disabled)
 - 3.3.3.3 Vacuum level setting (sensor enabled)
 - 3.3.3.4 Vacuum plus time setting (sensor enabled)
 - 3.3.3.5 Gas time setting (sensor disabled)
 - 3.3.3.6 Gas flush level setting (sensor enabled)
 - 3.3.3.7 Sealing time setting
 - 3.3.4 Vacuum cycle execution
 - 3.3.5 System monitor
 - 3.4 Daily cleaning
4. Trouble shooting
 - 4.1 Failure during a packaging cycle
 - 4.2 Insufficient vacuum
 - 4.2.1 Leakage in the bag
 - 4.2.2 No leakage in the bag
 - 4.2.3 Insufficient vacuum in the chamber
 - 4.3 Faulty seal
 - 4.3.1 Insufficient seal
 - 4.3.2 No seal
 - 4.3.3 Permanent sealing current
 - 4.3.4 Seal does not stick
 - 4.4 Fault in the valves
 - 4.5 Control board failure
5. Regular maintenance

2010-08-30

VACUUM PACKAGING MACHINES

1. SETTING UP THE MACHINE:

Before choosing the site for the machine, please consider that you will also need room for packaged and non-packaged products apart from the space needed for the machine itself.

Keep in mind that the machine must not be set up upon uneven ground. Especially with mobile models, the weight of the pump might then cause warping of the machine. Then the lid will not fit correctly.

Before starting to work, check the oil view glass on the pump, if there is a sufficient quantity of oil in the pump. Never use oil other than recommended by the producer. Never exceed maximum quantity of oil indicated, when adding or changing oil. Verify weekly.

Normal ambient temperature for the vacuum pump is between 10 to 70°C. For temperature below 10°C; it is recommended to use synthetic oil. Please consult factory and pump manufacturer manual for more information or when ambient temperature are outside normal limits.

2. ELECTRICAL CONNECTION:

Electrical connections must be made by qualified personnel. This person must make sure that the electrical entries correspond to the proper voltage and amperage of the machine. **GROUNDING INSTRUCTIONS:** This appliance must be grounded. In the event of malfunction or breakdown, grounding provides a path of least resistance for electric current to reduce the risk of electric shock. This appliance is equipped with a cord having an equipment-grounding conductor and a grounding plug. The plug must be plugged into an appropriate outlet that is properly installed and grounded in accordance with all local codes and ordinances.

DANGER Improper connection of the equipment-grounding conductor can result in a risk of electric shock. The conductor with insulation having an outer surface that is green with or without yellow stripes is the equipment-grounding conductor. If repair or replacement of the cord or plug is necessary, do not connect the equipment-grounding conductor to a live terminal. Check with a qualified electrician or serviceman if the grounding instructions are not completely understood, or if in doubt as to whether the appliance is properly grounded. Do not modify the plug provided with the appliance if it will not fit the outlet; have a proper outlet installed by a qualified electrician.

All vacuum machines are supplied with an electrical schematic drawing. An important step in connecting the machine is to make sure that the pump turns in its correct rotation.



The pump should not rotate more than 3 to 4 seconds in the wrong rotation or it may cause serious damage. The proper rotation is indicated by an arrow on the pump motor.


3. OPERATION:

3.1 Working principles:

A vacuum packaging cycle is made of 3 stages. First the vacuum is made, the air is completely taken out of the chamber and from bag containing the product. (See figure 1). Then it is possible to inject neutral gas from the nozzles, if the product is delicate. Finally, a mechanism pushes the sealing bar to the rubber support to seal the bag.

To obtain nice packages, the products and the bags have to be of proportional sizes. The bag's opening should never exceed 50 cm(2") past the seal bars. The product should be centered in height in relation to the seal bar by adjusting the spacers provided.

To obtain a good seal, make sure that no residue of fat is left between the bag's inner sides where sealing is done.



3.2 Special packaging:

3.2.1 Gas flushing (option):

There is an atmospheric pressure of 1 kg/ sq. cm (14 lbs/sq. inch) upon products when

fully evacuated. Products which can be damaged by high pressure must be packaged with a partial vacuum, or the pressure must be counterbalance by inflating the bag with gas (nitrogen or carbon dioxide) before sealing after evacuation.

For gas flushing, the bags are placed on the sealing bars, the open end placed over the gas nozzles mounted alongside the sealing bar. After evacuation, the vacuum valve closes and the gas valve opens. Gas time (sec.) can be set in the program menu.

The necessary gas tank and pressure valve mounted on tank is not supplied, The pressure of the gas regulator should be set at approximately 1/3 kg/sq. cm (5 lbs/sq.inch.). Each machine has an adaptor for gas connection when gas flush option is ordered.

3.2.2 Electrical bag cut (optional):

This option is used to obtain a package that the excess bagtail is cut off close to the seal (cannot be used with top and bottom sealing).

3.3 Vacuum packaging operation:

Note: Refer to the menus structure on page 13 and the keyboard detail on page 14.

3.3.1 Basics:

Use key "POWER" to power ON / OFF the vacuum packaging machine. When the unit is energized, the identification of the last executed program is displayed on LCD screen. To disconnect, use the "POWER" key to turn off the machine , then remove plug from outlet. Do not unplug by pulling on cord. To unplug, grasp the plug, not the cord. Unplug from outlet when not in use and before servicing or cleaning.

Use the "ESC" key to change over from the programs menu to the functions menu and from the functions menu to the programs menu.

In functions menu, use key "SELECT" to select a function and key "ENTER" to accede and executed the selection.

In programs menu, use key "SELECT" to select a program and key "ENTER" to accede and modify the selection.

In programs submenu, use key "ENTER" to pass over the parameters and point to the following one; the parameters are blinking to point out the acquisition mode. A return to programs menu is performed automatically following the last parameter acquisition.

In program submenu, use key "ESC" to get back to the programs menu. Strike any key to clear the error messages which may be displayed on LCD screen.

3.3.2 Functions menu:

3.3.2.1 Create a program:

When executing the "create a program" function, the program submenu is acceded, starting with the identification. The initial identification "Pxx NO NAME" is given to the program and all parameters are established to zero; the program number is allocated automatically.

3.3.2.2 Delete a program:

When executing the "delete a program" function, the programs menu is acceded and the number of the first program in memory is blinking to point out the deletion mode. Use key "SELECT" to select a program and key "ENTER" to accede and confirm deletion of the selection. Use key "ESC" to unconfirm a deletion and to leave the function. When leaving the function, the number of the actual program on LCD screen cease to blink.

3.3.2.3 Select operating mode:

When executing the "select operating mode" function, which is available only for the automatic units, the actual selection is blinking to point out the acquisition mode. Use key "SELECT" to get through the operating modes, which are automatic, semi-automatic and manual; the validation of the selected operating mode is performed automatically. Use key "ESC" or "ENTER" to leave the function and get back to the program menu.

3.3.3 Programs menu:

3.3.3.1 Program identification:

For a selected program, set the identification, using the numeric keyboard characters chart; press numeric key until the desired character is selected (4 times for the numeric value). Use key "ENTER" to validate the character and to validate the characters string at the end(the new characters string is blinking). In a middle of an acquisition, use key "ESC" to come backward and erase one or several characters.

Example: EXAMPLE 1 (9 characters)	→	keys 2, 2, ENTER	→	E
		keys 8, 8, 8, ENTER	→	X
		keys 1, ENTER	→	A
		keys 5, ENTER	→	M
		keys 6, ENTER	→	P
		keys 4, 4, 4, ENTER	→	L
		keys 2, 2, ENTER	→	E
		keys 9, 9, 9, ENTER	→	space
		keys 1, 1, 1, 1, ENTER	→	1
		key ENTER to validate the characters string		

3.3.3.2 Vacuum time setting (sensor disabled):

For a selected program set the vacuum time, in seconds; the validation is automatically performed following the second digit entry (the new vacuum time is blinking). In a middle of an acquisition, use key "ENTER" to validate the vacuum time and key "ESC" to come backward and start over with a new acquisition (the old vacuum time is blinking).

Examples: 1s → keys 0, 1 or 1, ENTER
15s → keys 1, 5

3.3.3.3 Vacuum level setting (sensor enabled)

For a selected program set the vacuum level, starting with the values; the decimal point is automatically inserted following the second digit entry and the validation is automatically performed following the third digit entry (the new vacuum level is blinking). The vacuum level is rounded off to the nearest half value. In the middle of an acquisition, use key "ENTER" to validate the vacuum level and key "ESC" to come backward and start over with a new acquisition (the old vacuum level is blinking). Set vacuum level to zero to bypass the pressure transducer and proceed only using the vacuum plus time.

Examples: 90.0% → keys 9, 0, 0 or 9, 0, ENTER or
keys 9, 0, 1 or 9, 0, 2 or 9, 0, 3 or 9, 0, 4
97.5% → keys 9, 7, 5 or
keys 9, 7, 6 or 9, 0, 7 or 9, 0, 8 or 9, 0, 9
0.0% → keys 0, 0, 0 or 0, ENTER

3.3.3.4 Vacuum plus time setting (sensor enabled)

For a selected program set the vacuum plus time, in seconds; the validation is automatically performed following the second digit entry (the new vacuum plus time is blinking). In a middle of an acquisition, use key "ENTER" to validate the vacuum plus time and key "ESC" to come backward and start over with a new acquisition (the old vacuum plus time is blinking).

Examples: 1s → keys 0, 1 or 1, ENTER
15s → keys 1, 5

3.3.3.5 Gas time setting (sensor disabled)

For a selected program set the gas time setting following the same procedure as for the vacuum time. Keep in mind that increasing gas time decrease sealing pressure. Some vacuum must be kept inside to assure proper functioning.

3.3.3.6 Gas flush level setting: (sensor enabled)

For a selected program set the gas flush level following the same procedure as for the vacuum level; the maximum gas flush level setting is 10% below the vacuum setting.

3.3.3.7 Sealing time setting:

For a selected program set the sealing, starting with the seconds; the decimal point is automatically inserted following the first digit entry and the validation is automatically performed following the third digit entry (the new sealing time is blinking). The sealing time is truncated to the nearest half hundredth. In a middle of an acquisition, use key "ENTER" to validate the sealing time and key "ESC" to come backward and start over with a new acquisition (the old sealing time is blinking).

Examples: 4.50s → keys 4, 5, 0 or 4, 5, ENTER or
keys 4, 5, 1 or 4, 5, 2 or 4, 5, 3 or 4, 5, 4
2.35s → keys 2, 3, 5 or
keys 2, 3, 6 or 2, 3, 7 or 2, 3, 8 or 2, 3, 9
0.00s → keys 0, 0, 0 or 0, ENTER

3.3.4 Vacuum cycle execution:

For the manual units and the automatic units set on manual, close the cover to initiate a vacuum cycle. For the automatic units set on semi-automatic or on automatic, use push button "STOP / START" to initiate or interrupt a vacuum cycle. A selected program can be initiated only in the programs menu, when no modifications are in progress, and the access to the other programs and functions is denied. During cycle execution the operation status is sequentially displayed on LCD screen, except for the parameters established to zero, which are not displayed:

- Vacuum time or vacuum % status during vacuum sequence,
- Gas time or gas % status during gas flush sequence,
- Sealing time status during sealing sequence,
- ATM message during atmosphere sequence.

During cycle execution, use key "1" to abort the vacuum sequence and execute the following sequence, which is gas flush or sealing, and key "ENTER" to accede and modify the program; the parameters become valid only for the following vacuum cycles.

3.3.5 System monitor:


To accede the diagnostics menu, power up the vacuum packaging machine while keeping pushed in the "ESC"key. Use key "SELECT" to select the system monitor function and key "ENTER" to accede and visualize the monitored parameters. Use key "SELECT" to change over from the software revision, the amount of working hours done and the amount of complete cycles performed since first initialization.

-MENUS STRUCTURE-

- **Functions menu:**
 - "F1 CREATE A PRGM"
 - "F2 DELETE A PRGM"
 - "F3 SELECT OPMODE" (automatic units only)
- **Programs menu:**
 - "Pxx NAME"
 - Program submenu:
 - "VACUUM: xx.x%" (10.0% - 99.5%)
 - "VACUUM PLUS: xxs" (0s - 99s)
 - "VACUUM: xx.xs" (10 – 199s) (sensor disabled in D8 menu)
 - "GAS FLUSH: xx.xs" (0 – 99s) (units with gas option) (sensor disabled in D8)
 - "GAS FLUSH: xx.x%" (0.0% - 10% below the vacuum level) (units with gas option)
 - "SEAL TIME: x.xxs" (0.00s - maximum unit allocated setting)
 - "Pxx NAME" (12 characters)
- **Diagnostics menu** (keys "ESC" & "POWER" for access):
 - "DIAGNOSTICS MENU" (access code required)
 - "D1 INPUTS TEST"
 - "D2 OUTPUTS TEST"
 - "D3 MODEL SELECT"
 - "D4 GAS OPTION"
 - "D5 SEALING TIME"
 - "D6 COOLING TIME"
 - "D7 OFFSET CALIB"
 - "D8 VACUUM SENSOR"
 - "D9 SIPROMAC PUB"
 - "D10 LOADING TIME" (automatic units only)
 - "D11 UNLOADNG TIME" (automatic units only)
 - "SYSTEM MONITOR" (no access code required)
 - "SOFTWARE: R x.xx"
 - "WORK HRS: xxxxx"
 - "CYCLES: xxxxxxxx"

-KEYBOARD DETAILS-

MC-40 CONTROLS





WARNING: All electrical work described in this brochure should be done by a QUALIFIED and AUTHORIZED technician.

3.4 Daily cleaning:

For hygienic cleanliness, it is imperative to clean chamber and spacers daily. Also clean the lid rubber to assure tight seat of the lid.

Cleaning instructions for gas injection nozzles: Periodically on a regular basis the gas injection nozzles must be removed with the connection tube and soaked in a food grade soap and water solution, then dried and re-installed.

4. TROUBLE SHOOTING:

4.1 Failure during packaging cycle:

4.1.1 "VACUUM ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the vacuum sequence within a preset period of time.

- Check vacuum lines for potential leaks or kinks.

4.1.2 "GAS FLUSH ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the gas flush sequence within a preset period of time.

- Check gas flush and vacuum lines for potential leaks or kinks.

4.1.3 "ATMOSPHERE ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the atmosphere sequence within a preset period of time.

- Check vacuum lines for potential leaks or kinks.

4.1.4 "COVER DOWN ERROR" message is displayed on LCD(manual units):

The input signal of the down position switch has been lost during cycle execution.

- Check limit switch adjustment.

4.2 Insufficient vacuum:

4.2.1 Leakage in the bag:

Most frequently, insufficient vacuum in bags is due to leakage in bag and not due to any fault of the machine.

Pin-hole leak for which there is no obvious explanation is due to faulty bag material.

Pin-hole leak caused by sharp edge of the product (bone, etc.). Use bone-guard or thicker film.

Tear in bag by careless handling (sharp edge on filling table, damage made by retailer or customer).

Leakage in lateral or bottom seal, complain to supplier of bags or film.

4.2.2 No leakage in the bag:

Bag is too large, therefore the surplus of air remains visible (there is surplus of air in 0.4% of the bag volume in each bag). Use bags of suitable size.

Vacuum level is too low:

Pressure bar is jammed and closes opening of bag during evacuation.

4.2.3 Insufficient vacuum in chamber:

If troubles described under 4.2.1 and 4.2.2 do not apply, there is something wrong with the evacuation. To find the leakage quickly, check for leaks with a precision vacuumeter, going back step by step from the chamber to the pump.

At the chamber (measuring point at base of valve) at maximum time of evacuation. If more than 6 torr, proceed directly to the pump, if more than 3 torr: have pump service by pump supplier. If pressure at pump is good, reconnect hoses to pump and measure again.

Verify at vacuum hose connections and valve connections.

When proceeding this way, starting from pump, loss of pressure per step must not exceed 0.5 to 1 torr.

Caution: Verify connections of measuring equipment before verifying machine.

Most frequent points of leakage: lid gasket, damaged vacuum hose or loose hose clamps.

4.3 Faulty seal:

4.3.1 Insufficient seal:

Damaged teflon or silicone rubber.

Sealing pressure too low, bellows leaking or pressure bar jammed.

Leakers in seal: heating wire mechanically damaged (knicked) or silicone rubber uneven.

4.3.2 No seal:

Sealing wire burnt.

Faulty contact in sealing circuit.

Sealing transformer burnt through.

Contactor does not work.

4.3.3 Permanent sealing current:

Contactor is jammed check sealing transformer for damage through overload.

4.3.4 Seal does not stick:

Insufficient layer of polyethylene (inferior quality of bags).

Seal area extremely contaminated by fat or meat juice. Use filling aid.

Sealing temperature is too low (when using very thick films).

Caution: Do not increase sealing time more than really necessary; higher temperature will reduce working life of teflon and silicone rubber.

4.4 Fault in the valve:

Vacuum or air valve does not open.

Check whether there is voltage on the magnetic valves during their period of operation. If there is no voltage a wire is broken or the PC board is damaged.

Lid does not open at the end of the cycle; air enters, but there is still 20 - 40% vacuum in chamber. Vacuum valve does not close.

4.5 MC40 Control board failure

NOTE: Refer to menu structure on page 12.

This board software is allowing access to a "Diagnostics Menu". Only qualified service technicians are authorized to access this menu by entering a security password.

By acceding either the "D1 input test" feature or the "D2 output test" feature, a trained technician will be able to quickly know the origin of the problem: pump, sealing system, pneumatic problem, security switches problem, etc...

Keep in mind that in most cases trouble is due to a leakage, loose electrical connection or evident damage to the main components: vacuum pump, valves, electrical contactors, thermal overload, fuses holder or transformer.

For assistance do not hesitate to contact your local service technicians.

5. Regular maintenance:

Routine controls to be made at regular intervals:

Check teflon for wear.

Check silicone rubber for burnt spots and smooth even position.

Check pressure bar for jamming.

Check lid sealing for damage and hardened spots.

Check switch-point of micro switch, adjust if necessary.


Check evacuation hose for damage (contraction of diameter, or abrasions).

Check vacuum connections for tightness.


Check oil in pump (oil level in view glass; add if necessary. Regular change of oil - necessity indicated by change of color).

Check vacuum in chamber with precision vacuumeter.

Check function of cycle with various settings of timers.



MECHANICAL DRAWING




ITEM	PART #	DESCRIPTION	QTY.
1	005B0602	MC-40 STRUCTURE ASSEMBLY	1
2	005-0531	TABLE ASSEMBLY	1
3	005-0540	COVER ASSEMBLY	1
4	005-0530	9 1/2" PLEXI COVER ASS'Y (OPT.)	1
5	005A0533	LEFT GAS INJECTION BAR ASS'Y (OPT.)	1
6	005A0808	RIGHT GAS INJECTION BAR ASS'Y (OPT.)	1
7	008-0464	GAS INJECTION CONNECTION TUBE (OPT.)	2
8	005-0564	SEAL BAR ASSEMBLY W/ SUPPORT	2
9	005-0565	SEAL BAR ASS'Y W/ SUPPORT (BAG CUT OPT.)	2
10	005-0532	BELLOWS ASSEMBLY	2
11	051-0780	FLAT WASHER 3/8" S/S	2
12	051-0620	HEX. NUT 3/8"-16 NC. S/S	2
13	051-0581	HEX. NUT 1/4"-20 NC. NYLON LOCK S/S	8
14	002-0326	LEFT/SEAL BAR GUIDE BLOCK	2
15	002-0327	RIGHT/SEAL BAR GUIDE BLOCK	2
16	051-0250	HEX. BOLT 1/4"-20 NC. X 1 1/2" S/S	8
17	051-0740	FLAT WASHER 1/4" S/S	16
18	005-0534	FILLER PLATE ASSEMBLY	2
19	051-0591	ACORN NUT 1/4"-20 NC. S/S	4
20	051-0740	FLAT WASHER 1/4" S/S	4
21	005A0583	P.C. BOARD SUPPORT ASSEMBLY	1
22	057-0089	1/4" x 5/8" O.D. EPDM RUB. SEAL WASHER	4

--W/GAS INJECTION--

-NOTE:-

FOR GAS INJECTION
KIT INSTALLATION
SEE DRAWING
010-0029


--W/O GAS INJECTION--



MACHINE		450A	
PART		450A MC-40 FRONT VIEW	
DATE	05-09-01	BY	M.A. LEBLANC
APP.		DATE	05-09-01
SIPROMAC		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
N.T.S.		N.T.S.	
M-I		M-I	
005A0601		005A0601	

0	REDRAWN	05-09-01	M.A.L.
LET.	MODIFICATION	DATE	INT.

1005-0607



ITEM	#PART	DESCRIPTION	QT.	ITEM	#PART	DESCRIPTION	QT.
45	052-3110	HEX. NUT 5/16"-18 NC. ZINC	16	1	005-0601	450A MC-40 FRONT VIEW	1
46	004A1651	COVER HOLD DOWN PRE-ASSY	1	2	005-0540	COVER ASSEMBLY	1
47	026-0610	LIMIT SWITCH LONG ROLLER	1	3	005-0530	9 1/2" COVER ASSEMBLY (OPTION)	1
48	051-0094	SCREW 4-40 X 1 1/2" FLAT SLOT SS	2	4	051-0185	SCREW 1/4"-20 NC. X 1/2" PAN PHILL. S/S	4
49	051-0715	WASHER #4 LOCK SS	2	5	051-0740	FLAT WASHER 1/4" S/S	16
50	051-0540	NUT #4-40 HEX S/S	2	6	001-1435	SPRING COVER	1
51	051-0790	WASHER 1/2" FLAT S/S	1	7	051-0620	HEX. NUT 3/8"-16 NC. S/S	12
52	004A2962	REAR PANEL ASSEMBLY (OPTION 63M3)	1	8	001-1335	CHAMBER STOPPER	1
53	004A2963	REAR PANEL ASSEMBLY	1	9	051-0783	FLAT WASHER 3/8" (THICK) S/S	25
54	052-0420	SCREW 1/4"-20 NC. X 3/4" PAN SLOT BRASS	4	10	051-0360	HEX. BOLT 3/8"-16 NC. X 1" S/S	8
				11	004-0129	COVER AXIS PRE-ASSEMBLY	1
				12	051-0630	HEX. NUT 1/2"-13 NC. S/S	2
				13	051-0581	HEX. NUT 1/4"-20 NC. NYLON LOCK	7
				14	008-0460	COVER SPRING	1
				15	005-0346	SPRING TENSION SUPPORT PRE-ASSY	1
				16	004-0276	CENTRAL COVER AXIS SUPPORT	1
				17	001-1540	CENTRAL COVER AXIS SUPPORT FIXATION	1
				18	051-0178	SET SCREW 1/4"-20 NC. X 5/16" S/S	1
				19	005-0348	MICRO-SWITCH COLLAR ASSY	1
				20	004-0274	LEFT COVER AXIS SUPPORT	1
				21	004-0275	RIGHT COVER AXIS SUPPORT	1
				22	051-0424	HEX. BOLT 3/8"-16 NC. 3 1/2" S/S	4
				23	051-0360	HEX. BOLT 3/8"-16 NC. 1 1/4" S/S	2
				24	038-0350	SLIT COORUG LOOM 2" ID X 370 MM	1
				25	057-0330	CABLE TIES 14" LONG BLACK	3
				26	001A2810	UPPER ELECTRICAL BOX SUPPORT	1
				27	051-0180	HEX. BOLT 1/4"-20 NC. X 1 1/2" S/S	11
				28	005-0347	ELECTRICAL BOX PRE-ASSEMBLY	1
				29	004-0273	ELECTRICAL BOX COVER PRE-ASSEMBLY	1
				30	056-0020	SPRING NUT 1/4"-20 NC. STEEL	4
				31	114-2020	DRYER FILTER	1
				32	101-0200	STRAIGHT 1/4" MNPT X 1/4" HOSE	1
				33	101-0210	STRAIGHT 1/4" FNPT X 1/4" HOSE	1
				34	001-2062	DRYER SUPPORT	2
				35	005-0323	GAS INLET ASSEMBLY (OPTION)	1
				36	051-0180	HEX BOLT 1/4"-20NC X 1 1/2" S/S (OPTION)	1
				37	051-0740	FLAT WASHER 1/4" S/S (OPTION)	1
				38	051-0581	HEX NUT 1/4"-20NC NYLON LOCK S/S (OPTION)	1
				39	004-0287	"BUSH" PUMPS INSTALLATION	1
				40	004-0288	"LEYBOLD" PUMPS INSTALLATION	1
				41	130-4PHB	4" PL CASTER SWIVEL W/ BRAKE	2
				42	130-4PHO	4" PL CASTER SWIVEL W/O BRAKE	2
				43	052-0520	BOLT 5/16"-18 NC. X 3/4" ZINC	16
				44	051-0760	FLAT WASHER 5/16"-18 NC. ZINC	32

F	REPLACER 004-0172 PAR 001-1435	10-06-08	J.G.
E	AJOUTER 2 REAR PANELS & BOLTS	09-05-20	J.G.
D	AJOUTER ITEM #51	08-02-22	J.G.
C	CHANGED SPRING POSITION NOTE	05-01-18	D.A.
B	ADDED PARTS #17 TO #50 WAS 005-0839	04-11-23	M.A.L.
A	MODIF. #A-0051 AJOUT COVER HOLD DOWN	03-02-14	J.G.
LET.	MODIFICATION	DATE	INT.

37

36

31

33

52

53


--DETAIL B--

OPTION MC-40

MACHINE	450A		SIPROMAC	
PART	MC-40 REAR VIEW		ST-GERMAIN DE GRANTHAU QUEBEC CANADA	
ITEM#	CHG#	DATE	M-I	QTY
		98-05-28		1
MAT:	ENG:	J.M.		
	APP:	DATE	10-06-11	

005-0564


ITEM	PART #	DESCRIPTION	QT.
1	004-0352	SEAL BAR PRE-ASSEMBLY	1
2	002-0512	SEAL BAR SUPPORT	1
3	051-0256	BOLT 1/4"-20nc. X 1 3/4" CAP SKT S/S	3
4	001-1960	EXTERIOR BELLOW COVER	1
5	001-1856	EXTERIOR BELLOW COVER	1
6	001-1858	SEAL BAR GUIDE	2
7	051-0740	WASHER 1/4" FLAT S/S	10
8	051-0250	BOLT 1/4"-20nc. X 1 1/2" S/S	4
9	051-0581	NUT 1/4"-20 NYLON LOCK S/S	6
10	038-0230	WIRING DUCT W/ ADHESIVE BACKING (0.35" x 0.5" x 300 (1.03))	1
11	051-0230	HEX BOLT 1/4-20 x 1 1/4" SS	2
12	001A5692	WIRE LOOM SUPPORT #2	2



COLLER CENTRÉ SUR ITEM #4 (10) CLUE ON ITEM #4 CENTERED

-CE CÔTÉ DU SUPPORT ÉGAL AVEC DE LA BARRE DE SCELLAGE
-THIS SIDE OF SUPPORT TO FIT FLUSH W/ SEAL BAR.

-ITEM #2 ÉGAL AVEC L'ITEM #4 & #5.
-ITEM #2 FLUSH WITH ITEM #4 & #5.




-END VIEW-

MACHINE		400, 450T & 450A		SIPROMAC	
PART		SEAL BAR ASSEMBLY W/SUPPORT		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
ITEM		CNC		M-I(M) QTY. 2	
DATE		11-08-30		NO. 005-0564	
APP. BY		J.G.		DATE 11-01-01	
MAT.					
RECESSINE S.E. & AJOUTER 001A5692		11-08-30		J.G.	
MODIFICATION		DATE		INT.	

004-0352

ITEM	#PART	DESCRIPTION	QT.
1	002-0481	SEAL BAR (TABLE)	1
2	002-0031	CONNECTOR	2
3	039-0200	SEALING ELEM. STD TWIN (2x626mm EA.)	4.31
4	052-0395	SCREW 1/4"-20 NC. X 5/16" SET HEX SKT OVAL PT	4
5	052-0250	SCREW #8-32 X 1 1/2" RND SLOT BRASS	2
6	051-0550	NUT #8-32 S/S	4
7	176-0200	TEFLON TAPE 5S ADHESIVE X 2" X (496mm EA.)	0.062
8	027-0400	CONNECTOR ADAPTOR 1/4" X #10 STUD	2




NOTE: - CUT OFF HEAD OF SCREW AFTER ASSEMBLING

E	ADDED 450T WAS 005-0377	08-05-26	D.A.
D	MODIFICATION #A-0398 (CONNECTEUR)	04-04-19	J.G.
C	ADDED 400	99-05-08	S.L
B	REDRAWN	98-02-10	A.P.
LET	MODIFICATION	DATE	INT

MACHINE		TOLERANCES		SIPROMAC
400, 450A & 450T		USURANCE TOLÉRANCE PERMISE	INCH 0.000" 0.015" 0.020"	ST-GERMAIN DE GRANTHAU QUEBEC CANADA
PART			N.T.S.	
SEAL BAR PRE-ASSEMBLY				
ITEM:	CNC		QTY. M-1	2
MATL	DWG APPR. <i>A.P.</i>	DATE 98-02-10	NO.	004-0352

1005-0565

ITEM	PART #	DESCRIPTION	QT.
1	004-0355	BAG CUT SEAL BAR PRE-ASSEMBLY	1
2	002-0512	SEAL BAR SUPPORT	1
3	051-0256	BOLT 1/4"-20nc. X 1 3/4" CAP SKT S/S	3
4	001-1960	EXTERIOR BELLOW COVER	1
5	001-1856	EXTERIOR BELLOW COVER	1
6	001-1858	SEAL BAR GUIDE	2
7	051-0740	WASHER 1/4" FLAT S/S	10
8	051-0250	BOLT 1/2"-20nc. X 1 1/2" S/S	4
9	051-0581	NUT 1/4"-20 NYLON LOCK S/S	6
10	038-0230	WIRING DUCT W/ ADHESIVE BACKING (0.35" x 0.5" x 300 (1.03))	1
11	051-0230	HEX BOLT 1/4-20 x 1 1/4" SS	2
12	001A5692	WIRE LOOM SUPPORT #2	2




-END VIEW-

-BAG CUT OPTION-

MACHINE		400, 450T & 450A		DEPT. TOL. METRIC INCH		SIPROMAC	
PART		SEAL BAR ASSEMBLY W/SUPPORT		USINAGE ±0.1 ±0.0307		ST-GERMAIN DE GRANTHAM	
ITEM		CNC		BOULAGE ±0.5 ±0.0207		QUÉBEC CANADA	
DATE		11-08-30		N.T.S.		M-I-(M) QTY. 2	
REDESSINE S.E. & AJOUTER 001A5692		11-08-30 J.G.		DATE		005-0565	
MODIFICATION		DATE		INT.			

ITEM	#PART	DESCRIPTION	QT.
1	002-0481	SEAL BAR	1
2	002-0031	CONNECTOR	2
3	039-0230	REFLEX BAND 2.5MM (626mm EA.)	0.063
4	039-0270	1" PROFILE CUT. ELEM. (626mm EA.)	0.063
5	052-0395	SCREW 1/4"-20 NC. X 5/16" SET HEX SKT OVAL PT	4
6	052-0250	SCREW #8-32 X 1 1/2" RND SLOT BRASS	2
7	051-0550	NUT #8-32 S/S	4
8	176-0200	TEFLON TAPE 5S ADHESIVE X 2" X (496mm EA.)	0.063
9	027-0400	CONNECTOR ADAPTOR 1/4" X #10 STUD	2



NOTE: - CUT OFF HEAD OF SCREW AFTER ASSEMBLING



E	ADDED 450T WAS 005-0383	08-05-26	D.A.
D	MODIFICATION #A-038B (CONNECTEUR)	04-04-19	J.G.
C	C ADDED 400	99-05-06	S.L.
B	REDRAWN	98-02-10	A.P.
LET.	MODIFICATION	DATE	INT.

~~—BAG CUT OPTION—~~




MACHINE 400, 450A & 450T	TOLERANCES FRACTIONAL DECIMAL MILLIMETRIC INCH		SIPROMAC ST-GERMAIN DE GRANTHAM QUEBEC CANADA
PART	US DRAWE ± 0.1 FRACTIONAL ± 0.005 DECIMAL ± 0.001 MILLIMETRIC ± 0.001 INCH		
SEAL BAR PRE-ASSEMBLY		N.T.S.	
ITEM#	QNC	NO.	2
MAT#	BY	DATE	98-02-10
APP.	APP.	DATE	02-03-98
		004-0355	

1005-0540

ITEM	#PART	DESCRIPTION	C
1	004-0354	COVER PRE-ASS'Y	
2	179-0020	NEOPRENE SPONGE 1/2"	8
3	004A0351	UPPER SEAL BAR PRE-ASS'Y	1
4	051-0255	BOLT 1/4" -20 x 1 3/4" S/S	1
5	051-0581	NUT 1/4" -20 NYLON LOCK S/S	1
6	051-0740	WASHER 1/4" FLAT S/S	1




-SECTION A-A-

MACHINE	400 & 450A		COVER ASSEMBLY		SIPROMAC	
PART					ST-GERMANN DE GRANTHAM QUEBEC CANADA	
ITEM			QING: _____		M 01 1	
DATE:						
	DWG	S/L	DATE	99-04-07	NO. 005-0540	
	APP.	DATE				

B	MODIFIED VIEW ITEM #3 (UPPER SEAL BAR)	00-01-24	S.L.
A	ADDED 400	99-05-07	S.L.
LET.	MODIFICATION	DATE	INT.

U04A0351


ITEM	PART #	DESCRIPTION	QT.
1	002A0480	UPPER SEAL BAR SUPPORT	1
2	008-0450	UPPER SEAL BAR RUBBER	1



MACHINE 400, 450T & 450A		INCH TOLERANCE 0 ± .015 0.005 ± .0005 0.000 ± .0005		SIPROMAC	
PART UPPER SEAL BAR PRE-ASS'Y		METRIC TOLERANCE 0 ± .5 0.005 ± .0005 0.000 ± .0005		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
ITEM: _____		N.T.S.		DEPT: M-I	
DATE: 99-08-02		DATE: 97-12-15		QT: 2	
BY: D.W.S. LAROUCHE		APP: _____		NO. 004A0351	

D	ADDED 450T WAS 004A0181	08-05-28	D.A.
C	REDRAWN	99-08-02	S.L.
LET.	MODIFICATION	DATE	INT.

ITEM	PART #	DESCRIPTION
1	004B0438	STRUCTURE PRE-ASS'Y
2	005A0584	REAR MC-40 SUPPORT ASSY.
3	051-0287	BOLT 1/4"-20 x 3 1/4"
4	051-0757	FLAT WASHER 1/4" THICK
5	058-0140	PLAST. SPACER .266" x 1/2" x 2 1/4"
6	051-0750	WASHER 1/4" LOCK SS
7	051-0580	NUT 1/4"-20
8	114-0260	VACUUM GAGE W/ SUPPORT
9	001-1869	HOLDING WASHER (FOR VAC. GAUGE)
10	101-0038	STR. 1/4" FNPT x 3/8" T.P. COMP. BR.



SEE INSTALLATION DETAIL

—UNE FOIS L'ITEM 2 INSTALLÉ, UTILISER DE L'ADHÉSIF MARIN 5200 #169-0210 POUR SCELLER LE HAUT, LES CÔTÉS ET LES COINS DU BAS (LE CÔTÉ DU DESSOUS N'EST PAS SCELLÉ)

—ONCE ITEM 2 IS INSTALLED, USE 169-0210 5200' MARINE ADHESIVE TO SEAL TOP, SIDES & BOTTOM CORNERS (UNDER SIDE NOT SEALED).



—INSTALLATION DETAIL—

MACHINE		450A		SIPROMAC	
PART		MC-40 STRUCTURE ASS'Y		ST-GERMAIN DE GRANTHA QUEBEC CANADA	
ITEM	CHG	DATE	05-09-02	QTY	1
DATE	05-11-04	DATE	05-11-04	QTY	1

REDRAIN	MODIFICATION	DATE	05-09-02	M.A.L.	INT.
---------	--------------	------	----------	--------	------

1005A0584

ITEM	PART #	DESCRIPTION	QT.
1	004A0426	REAR MC-40 SUPPORT PRE-ASS'Y	1
2	179-0019	U-CHANNEL BLACK EPDM FOAM (3.9)	1
3	057-0002	CABLE CLAMPS 9mm (11.2 X 9.3)	1




SECTION A

MACHINE 420A, 450T, 450A, 550A, 570A, 580A, 600A, 620A & 650A		DEPT. OF METALWORK		SIPROMAC	
PART REAR MC-40 SUPPORT ASS'Y		TOLERANCE 1.0.5 ± 0.020"		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
ITEM		N.T.S.		DEPT. M	
DATE 05-09-01		UNIT 26-10-24		QTY. 1	
DRAWN BY M.A.L.		DATE 05-09-01		005A0584	
APPROVED BY		DATE 26-10-24			

F	REDRAWN	050901	M.A.
LET.	MODIFICATION	DATE	INT.


005A0583

ITEM	PART #	DESCRIPTION	QT
1	004A0425	FRONT MC-40 SUPPORT PRE-ASSY	1
2	051-0092	SCREW #4-40 x 1 1/4" FLAT SLT S/S	4
3	051-0713	WASHER #4 FLAT S/S	4
4	058-0120	CPVC SPACER 0.120" x 1/4" x 5/8"	4
5	051-0540	NUT #4-40 HEX S/S	8
6	051-0715	WASHER #4 LOCK SS	4



033-0015 OR
033-0017 OR
033-0018 OR
KEY BOARD REF.
(NOT INCLUDED)

USE JIG TO INSTALL, IN REGARDS TO OPENINGS IN ITEM #1




MACHINE	420A, 450A, 450T, 500A, 500D, 550A, 580A, 600A, 620A & 650A	DEPT. 101	METRIC	INCH	USINAGE	1.01	± 0.004	TOLERANCE	1.05	± 0.002	SOUDEAGE	1.03	± 0.002	N.T.S.	ST-GERMAIN DE GRANTHAM QUEBEC CANADA	SIPROMAC
PART	FRONT MC-40 SUPPORT ASS'Y	CHC	DATE	05-09-01	APP. BY	M.A.L.	DATE	05-09-01	APP. BY	M.A.L.	DATE	05-09-01	APP. BY	M.A.L.	DATE	05-09-01
ITEM	FRONT MC-40 SUPPORT ASS'Y	CHC	DATE	05-09-01	APP. BY	M.A.L.	DATE	05-09-01	APP. BY	M.A.L.	DATE	05-09-01	APP. BY	M.A.L.	DATE	05-09-01
MAT.																

H	AJOUTER 500D	08-04-17	J.G.
G	REDRAWN	05-09-01	M.A.
LET.	MODIFICATION	DATE	INT.

005A0583

1005A0780


ITEM	PART #	DESCRIPTION	QT
1	004A3167	REAR MC-40 SUPPORT PRE-ASSY	1
2	057-0002	CABLE CLAMPS 9mm (11,2 X 9,3)	1
3	179-0019	U-CHANNEL BLACK EPDM FOAM (4,5265)	1
4	036-0409	PRESSE-ETOUPE CD13	3
5	051-0757	WASHER 1/4" FLAT THICK S/S	4
6	051-02885	BOLT 1/4"-20 x 3-3/4" HEX SS	4
7	058-0139	NYLON SPACER 1/4" ID X 1/2" OD X 2-1/8"	4
8	058-0025	NYLON SPACER 0.257"ID x 0.500"OD x 1/4"	8
9	051-0750	WASHER 1/4" LOCK S/S	4
10	051-0580	NUT 1/4"-20 S/S	4
11	058-0016	NYLON SPACER .252"ID X 1/2"OD X 1/8"THK	4



COUPER AVEC DES PINCES
ICI DES 2 CÔTÉS.

CUT OFF W/PLIERS
HERE BOTH SIDES.

UTILISER LES TROUS EXISTANTS DE LA
STRUCTURE LORS DE L'INSTALLATION.



PERCER DE NOUVEAUX TROUS DANS LA STRUCTURE LORS DE L'INSTALLATION.



DRILL NEW HOLES IN STRUCTURE
DURING INSTALLATION.

MACHINE	420A, 450A, 550A, 580A, 600A, 620A & 650A	DEPT. TOL. METRIC INCH ± 0.007 ± 0.007 TOLERIE ± 0.3 ± 0.3 SQUADAGE ± 0.5 ± 0.020"		SIPROMAC ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
PART	REAR MC-40 SUPPORT ASS'Y (OPT. HEATER)	N.T.S.			
ITEM		ENC		DEPT.	
MANU.		DWG BY M.D.		DATE 10-02-03	
		APP. BY		QTY. 1	
				M-(M)-1 QTY. 1	
				NO. 005A0780	

LET	MODIFICATION		DATE	INT.
A	AJOUTER ITEM 058-0016 ET 058-0139 ETAT 058-0140		10-09-01	J.G.


1005A0779

ITEM	PART #	DESCRIPTION	QTY.
1	004A3166	FRONT MC-40 SUPPORT PRE-ASSY(OPT. HEATER)	1
2	051-0092	SCREW #4-40 x 1 1/4" FLAT SLT S/S	4
3	051-0713	WASHER #4 FLAT S/S	4
4	058-0120	CPVC SPACER 0.120" x 1/4" x 5/8"	4
5	051-0540	NUT #4-40 HEX S/S	8
6	051-0715	WASHER #4 LOCK SS	4
7	057-0089	1/4" x 5/8" O.D. EPDM RUB. SEAL, WASHER	4
8	051-0740	WASHER 1/4" FLAT S/S	4
9	051-0591	NUT 1/4"-20 ACORN S/S	4




MACHINE		420A, 450A, 550A, 580A, 600A, 620A & 650A		DEPT. TOL. METRIC		RICH		STIPROMAC	
PART		FRONT MC-40 SUPPORT ASSY(OPT. HEATER)		USURAGE		± 0.004		ST GERMAIN DE GRANTHAM	
ITEM		GNC		N.T.S.		± 0.1		QUEBEC CANADA	
DATE		10-02-03		DATE		10-02-05		005A0779	
MODIFICATION		DATE		INT.		DATE		INT.	


ITEM	PART #	DESCRIPTION	QT.
1	001-1341	ELECTRICAL BOX COVER	1
2	179-0004	NEOPRENE SPONGE 1/8" X 1/2" ADHESIVE	1
3	127-0100	"CAUTION" YELLOW STICKER	1



FRONT VIEW-




—REAR VIEW—

MACHINE	450A & 550A		METRIC TOLERANCE 0 ± .5 .0 ± .05 .00 ± .005 .000 ± .0005	INCH TOLERANCE 0 ± .015 .00 ± .005 .000 ± .0005	SIPROMAC
PART	E-BOX COVER PRE-ASS'Y		N.T.S.		ST-GERMAIN DE GRANTHAM QUEBEC CANADA
ITEM#	CNC		SCALE		DT. 1
MAT#	DWG A.P. BY APP. 		DATE 97-01-08		NO. 004-0273
MODIFICATION		DATE	INT.		


1005-0534

ITEM	PART #	DESCRIPTION	QT.
1	008-0455	FILLER PLATE	2
2	003-0080	FILLER PLATE FOOT	8
3	054-0004	METAL SCREW #10 X 1" FLAT SLOT S/S	8






INSTALLATION DETAIL

MACHINE 400 & 450A		SIPROMAC		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
PART FILLER PLATE ASSEMBLY		INCH TOLERANCE 0.0 ± .015 0.00 ± .0005 N.T.S.		SCALE 2	
ITEM: _____		METRIC TOLERANCE 0.0 ± .05 0.00 ± .0005 ANGLE ± 1°		DATE 97-08-21	
CNC: _____		DWG BY A. PROVENCHER		DATE	
MAT: _____		APP. _____		NO. 005-0534	
C	ADDED 400	99-05-07	S.L.		
B	REDRAWN/ MODIF. NO. A-0215	97-08-21	A.P.		
LET.	MODIFICATION	DATE	INT.		




ELECTRICAL DRAWING






category	VACUUM PACK	model	450A	volt	3Ph 60Hz							SIPROMAC St-Germain de Grantham QUEBEC,CANADA						
system	MC-40			circuit	power		year	month	day	block								
usual																		
fonctions																		
options												concept	draw	app	006-0730			PAGE 1 de 1
							XX	PP	DL									

TRANSF.CONT.



category	VACUUM PACK	model	450A	vol.	ALL				SIPROMAC					
system	MC-40			circuit	control		year	month	day	block	St-Germain de Grantham			
usual							10	07	08		QUEBEC, CANADA			
fonctions								concept	draw	app				
options								XX	PP	DL	006-0737			
												PAGE 1 de 2		




category	VACUUM PACK	model	450A	volt.	ALL	ALL				SIPROMAC			
system	MC-40					year	month	day	block	St-Germain de Grantham			
usual						10	07	08		QUEBEC, CANADA			
functions						concept	draw	app	DL	006-0737			
options						XX	PP	DL		PAGE 2 de 2			



# SIPRO	PART DESCRIPTION	PART APPLICATION	MACHINE VOLTAGE	MACHINE	REF.	OPT.	QTY
028-0018	TERMINAL BLOCK M6/8 600V/50A.(8AWG)	SUPPLY	208V/3PH/60HZ	450A	L1-L2-L3		3
028-0020	GROUND TERMINAL BLOCK M6/8P	SUPPLY	208V/3PH/60HZ	450A	GND		1
028-0060	SEPARATOR M4/6	SUPPLY	208V/3PH/60HZ	450A	GND-L1-L2-L3		4
028-0105	GROUND BARRIER (6 HOLES)	SUPPLY	ALL	450A	GND		1
034-0700	FUSE HOLDER 30A/600V GOULD	VACUUM	208V/3PH/60HZ	450A	F1		3
034-0500	FUSE MIDGET 15A/250V TIME-DELAY	VACUUM RA-0040	208V/3PH/60HZ	450A	F1	A1	3
025-0030	MOTOR CONTACTOR 2HP IN 208V/3PH-CSA,UL	VACUUM RA-0040	208V/3PH/60HZ	450A	C1	A1	1
025-0160	THERMAL OVERLOAD 5.5 TO 8A-CSA,UL	VACUUM RA-0040	208V/3PH/60HZ	450A	O/L1	A1	1
030-0180	CAB TIRE	VACUUM RA-0040	208V/3PH/60HZ	450A	WM1	A1	2M.
125-0030	BUSCH RA-0040 230-460V/3PH/60HZ 2HP 6.2A	VACUUM RA-0040	208V/3PH/60HZ	450A	M1	A1	1
034-0530	FUSE MIDGET 20A/250V TIME-DELAY	VACUUM RA-0063	208V/3PH/60HZ	450A	F1	A2	3
025-0025	MOTOR CONTACTOR 3HP IN 208V/3PH-CSA,UL	VACUUM RA-0063	208V/3PH/60HZ	450A	C1	A2	1
025-0170	THERMAL OVERLOAD 7 TO 10A-CSA,UL	VACUUM RA-0063	208V/3PH/60HZ	450A	O/L1	A2	1
030-0180	CAB TIRE	VACUUM RA-0063	208V/3PH/60HZ	450A	WM1	A2	2M.
125-0040	BUSCH RA-0063 230-460V/3PH/60HZ 3HP 8.4A	VACUUM RA-0063	208V/3PH/60HZ	450A	M1	A2	1
034-0550	FUSE MIDGET 25A/250V TIME-DELAY	VACUUM RA-0100	208V/3PH/60HZ	450A	F1	A3	3
025-0030	MOTOR CONTACTOR 5HP IN 208V/3PH-CSA,UL	VACUUM RA-0100	208V/3PH/60HZ	450A	C1	A3	1
025-0190	THERMAL OVERLOAD 12 TO 18A-CSA,UL	VACUUM RA-0100	208V/3PH/60HZ	450A	O/L1	A3	1
030-0140	CAB TIRE	VACUUM RA-0100	208V/3PH/60HZ	450A	WM1	A3	2M.
125-0060	BUSCH RA-0100 230-460V/3PH/60HZ 5HP 13.6A	VACUUM RA-0100	208V/3PH/60HZ	450A	M1	A3	1
034-0700	FUSE HOLDER 30A/600V GOULD	SEALING	208V/3PH/60HZ	450A	F2		2
034-0450	FUSE MIDGET 7A/250V TIME-DELAY	SEALING	208V/3PH/60HZ	450A	F2		2
029-0040	TRANSFO 500VA/208-240/24V 60HZ	SEALING	208V/3PH/60HZ	450A	TR1		1
027-0220	TERMINAL ROUND STUD #10 600v 75°C	SEALING	ALL	450A	WEL		2
025-0020	CONTACTOR ITH=25A-CSA,UL	SEALING	ALL	450A	C2		1
030-0410	TEW #10/104 BLACK	SEALING	ALL	450A	WEL		7M.
027-0065	TERMINAL FLAG FEMALE YELLOW .250"	SEALING	ALL	450A	WEL		4
005-0564	SEAL BAR ASSEMBLY W/SUPPORT	SEALING TWIN SEAL	ALL	450A		B1	2
005-0565	SEAL BAR ASSEMBLY W/SUPPORT	SEALING BAG CUT	ALL	450A		B2	2
034-0740	FUSE HOLDER M4/8SF	CONTROL TRANSFO	208V/3PH/60HZ	450A	F5		2
034-0200	FUSE 5X20MM 3/4A 250V T-DELAY	CONTROL TRANSFO	208V/3PH/60HZ	450A	F5		2
029-0009	TRANSFO 65VA/208-230V/24-9V	CONTROL TRANSFO	208V/3PH/60HZ	450A	TR2		1
034-0740	FUSE HOLDER M4/8SF	CONTROL 9VAC+24VAC	ALL	450A	F3+F4		2
034-0210	FUSE 5X20MM 2A/250V TIME DELAY	CONTROL 9VAC	ALL	450A	F3		1
034-0240	FUSE 5X20MM 4A/250V TIME DELAY	CONTROL 24VAC	ALL	450A	F4		1
034-0740	FUSE HOLDER M4/8SF-CSA	HEATING PANEL(OPTION)	208V/3PH/60HZ	450A	F6	C	1
034-0200	FUSE 5x20MM 3/4A/250V TD-CSA	HEATING PANEL(OPTION)	208V/3PH/60HZ	450A	F6	C	1
030-0210	CAB TIRE 18/3 SJ-CSA	HEATING PANEL(OPTION)	208V/3PH/60HZ	450A	W6	C	2M.
039-0191	THERMOSTAT HAMMOND DIN RAIL	HEATING PANEL(OPTION)	208V/3PH/60HZ	450A	T6	C	1
039-0192	HEATER 15W	HEATING PANEL(OPTION)	208V/3PH/60HZ	450A	H6	C	1
030-0590	20AWG/12COND.PVC,UNSHIELD.300V	OUTPUT CONTROL	ALL	450A	W001		2.5M.

# SIPRO	PART DESCRIPTION	PART APPLICATION	MACHINE VOLTAGE	MACHINE	REF.	OPT.	QTY
036-0740	12 CONTACTS CONNECTOR	OUTPUT CONTROL	ALL	450A	JP3/1-2		1
030-0631	22AWG/4COND.PVC,SHIELDED,300V.	INPUT CONTROL	ALL	450A	WCV		2.5M.
036-0820	0.156" CENTERLINE CRIMP HOUSING	INPUT CONTROL	ALL	450A	JP4		1
036-0850	0.156" CENTERLINE CRIMP TERMINAL	INPUT CONTROL	ALL	450A	JP4		2
033-0038	MICROPROCESSOR MC-40 SENSOR VACUUM	CONTROL WITH SENSOR	ALL	450A	MC-40	D1	1
033-00385	MICROPROCESSOR MC-40 NO SENSOR VAC.	CONTROL W/O SENSOR	ALL	450A	MC-40	D2	1
033-0015	MEMBRANE MC-40 SIPROMAC	CONTROL SIPROMAC	ALL	450A		E1	1
033-0018	MEMBRANE MC-40 BERKEL	CONTROL BERKEL	ALL	450A		E2	1
106-0010	VALVE 2WAY 24V 1/4 NPT(G22) 60HZ	OPTION GAS	ALL	450A	H	F	1
106-0030	VALVE 2WAY 24V 3/4 NPT(G95) 60HZ	ATMOSPHERE	ALL	450A	F		1
106-0070	VALVE 3WAY 24V 1/4 NPT(G176)60HZ	BELLOWS	ALL	450A	G		1
026-0610	LIMIT SWITCH LONG ROLLER 15A 250V	COVER POSITION	ALL	450A	CV		1
028-0018	TERMINAL BLOCK M6/8 600V/50A.(8AWG)	SUPPLY	460V/3PH/60HZ	450A	L1-L2-L3		3
028-0020	GROUND TERMINAL BLOCK M6/8P	SUPPLY	460V/3PH/60HZ	450A	GND		1
028-0060	SEPARATOR M4/6	SUPPLY	460V/3PH/60HZ	450A	GND-L1-L2-L3		4
028-0105	GROUND BARRIER (6 HOLES)	SUPPLY	ALL	450A	GND		1
034-0700	FUSE HOLDER 30A/600V GOULD	VACUUM	460V/3PH/60HZ	450A	F1		3
034-0480	FUSE MIDGET 10A/600V FAST ACTING	VACUUM RA-0040	460V/3PH/60HZ	450A	F1	A1	3
025-0010	MOTOR CONTACTOR 5HP IN 460V/3PH-CSA,UL	VACUUM RA-0040	460V/3PH/60HZ	450A	C1	A1	1
025-0140	THERMAL OVERLOAD 2.5 TO 4A-CSA,UL	VACUUM RA-0040	460V/3PH/60HZ	450A	O/L1	A1	1
030-0190	CAB TIRE	VACUUM RA-0040	460V/3PH/60HZ	450A	WM1	A1	2M.
125-0030	BUSCH RA-0040 230-460V/3PH/60HZ 2HP 2.6A	VACUUM RA-0040	460V/3PH/60HZ	450A	M1	A1	1
034-0510	FUSE MIDGET 15A/600V FAST ACTING	VACUUM RA-0063	460V/3PH/60HZ	450A	F1	A2	3
025-0025	MOTOR CONTACTOR 7.5HP IN 460V/3PH-CSA,UL	VACUUM RA-0063	460V/3PH/60HZ	450A	C1	A2	1
025-0150	THERMAL OVERLOAD 4 TO 6A-CSA,UL	VACUUM RA-0063	460V/3PH/60HZ	450A	O/L1	A2	1
030-0190	CAB TIRE	VACUUM RA-0063	460V/3PH/60HZ	450A	WM1	A2	2M.
125-0040	BUSCH RA-0063 230-460V/3PH/60HZ 3HP 3.9A	VACUUM RA-0063	460V/3PH/60HZ	450A	M1	A2	1
034-0540	FUSE MIDGET 20A/600V FAST ACTING	VACUUM RA-0100	460V/3PH/60HZ	450A	F1	A3	3
025-0010	MOTOR CONTACTOR 5HP IN 460/3PH-CSA,UL	VACUUM RA-0100	460V/3PH/60HZ	450A	C1	A3	1
025-0160	THERMAL OVERLOAD 5.5 TO 8A-CSA,UL	VACUUM RA-0100	460V/3PH/60HZ	450A	O/L1	A3	1
030-0190	CAB TIRE	VACUUM RA-0100	460V/3PH/60HZ	450A	WM1	A3	2M.
125-0060	BUSCH RA-0100 230-460V/3PH/60HZ 5HP 6.3A	VACUUM RA-0100	460V/3PH/60HZ	450A	M1	A3	1
034-0700	FUSE HOLDER 30A/600V GOULD	SEALING	460V/3PH/60HZ	450A	F2		2
034-0430	FUSE MIDGET 4A/600V FAST ACTING	SEALING	460V/3PH/60HZ	450A	F2		2
029-0045	TRANSFO 500VA/220-400-460V/24V	SEALING	460V/3PH/60HZ	450A	TR1		1
027-0220	TERMINAL ROUND STUD #10 600v 75°C	SEALING	ALL	450A	WEL		2
025-0020	CONTACTOR ITH=25A-CSA,UL	SEALING	ALL	450A	C2		1
030-0410	TEW #10/104 BLACK	SEALING	ALL	450A	WEL		7M.
027-0065	TERMINAL FLAG FEMALE YELLOW .250"	SEALING	ALL	450A	WEL		4
005-0564	SEAL BAR ASSEMBLY W/SUPPORT	SEALING TWIN SEAL	ALL	450A		B1	2


# SIPRO	PART DESCRIPTION	PART APPLICATION	MACHINE VOLTAGE	MACHINE	REF.	OPT.	QTY
005-0565	SEAL BAR ASSEMBLY W/SUPPORT	SEALING BAG CUT	ALL	450A		B2	2
034-0700	FUSE HOLDER 30A/600V GOULD	CONTROL TRANSFO	460V/3PH/60HZ	450A	F5		2
034-0420	FUSE MIDGET 2A/600V FAST ACTING	CONTROL TRANSFO	460V/3PH/60HZ	450A	F5		2
029-0007	TRANSFO 65VA/220-380-460V/24-9	CONTROL TRANSFO	460V/3PH/60HZ	450A	TR2		1
034-0740	FUSE HOLDER M4/8SF	CONTROL 9VAC+24VAC	ALL	450A	F3+F4		2
034-0210	FUSE 5X20MM 2A/250V TIME DELAY	CONTROL 9VAC	ALL	450A	F3		1
034-0240	FUSE 5X20MM 4A/250V TIME DELAY	CONTROL 24VAC	ALL	450A	F4		1
030-0590	20AWG/12COND.PVC,UNSHIELD.300V	OUTPUT CONTROL	ALL	450A	W001		2.5M.
036-0740	12 CONTACTS CONNECTOR	OUTPUT CONTROL	ALL	450A	JP3/1-2		1
030-0631	22AWG/4COND.PVC,SHIELDED,300V.	INPUT CONTROL	ALL	450A	WCV		2.5M.
036-0820	0.156" CENTERLINE CRIMP HOUSING	INPUT CONTROL	ALL	450A	JP4		1
036-0850	0.156" CENTERLINE CRIMP TERMINAL	INPUT CONTROL	ALL	450A	JP4		2
033-0038	MICROPROCESSOR MC-40 SENSOR VACUUM	CONTROL WITH SENSOR	ALL	450A	MC-40	C1	1
033-00385	MICROPROCESSOR MC-40 NO SENSOR VAC.	CONTROL W/O SENSOR	ALL	450A	MC-40	C2	1
033-0015	MEMBRANE MC-40 SIPROMAC	CONTROL SIPROMAC	ALL	450A		D1	1
033-0018	MEMBRANE MC-40 BERKEL	CONTROL BERKEL	ALL	450A		D2	1
106-0010	VALVE 2WAY 24V 1/4 NPT(G22) 60HZ	OPTION GAS	ALL	450A	H	E	1
106-0030	VALVE 2WAY 24V 3/4 NPT(G95) 60HZ	ATMOSPHERE	ALL	450A	F		1
106-0070	VALVE 3WAY 24V 1/4 NPT(G176)60HZ	BELLOWS	ALL	450A	G		1
026-0610	LIMIT SWITCH LONG ROLLER 15A 250V	COVER POSITION	ALL	450A	CV		1



PNEUMATIC DRAWING




ITEM	PART #	DESCRIPTION	QTY
1	005-0410	MACHINE ASSEMBLY FRONT VIEW	1
2	005-0564	SEAL BAR ASSY W/ SUPPORT	2
3	005-0565	SEAL BAR ASSY W/ SUPPORT (BAG CUT OPT.)	2
4	005-0411	MACHINE ASSEMBLY REAR VIEW	1
5	005-0347	ELECTRICAL BOX ASSEMBLY	1
6	051-0740	FLAT WASHER 1/4" S.S.	4
7	051-0180	HEX.BOLT 1/4"-20 x 1/2" S.S.	4
8	004-0273	E-BOX COVER PRE-ASSY.	1
9	005A0808	RIGHT GAS INJECTION BAR ASSY.(OPT.)	1
10	005A0533	LEFT GAS INJECTION BAR ASSY.(OPT.)	1
11	008-0464	GAS INJECTION CONNECTION TUBE	2
12	005-0323	GAS INLET ASSEMBLY	1
13	051-0180	HEX. BOLT 1/4"-20 x 3/4" S.S.	1
14	051-0580	HEX. NUT 1/4"-20 S.S.	1
15	106-0010	SELENOID VALVE 2 WAY 1/4"NPT W/ SUPP.	1
16	051-0100	RND.H.SCREW #8-32 x 3/8" S.S.	2
17	051-0720	FLAT WASHER #8 S.S.	2
18	051-0550	HEX.NUT #8-32 S.S.	2
19	101-0036	STRAIGHT 1/4"NPT x 3/8" T.P.COMP.	1
20	101-0065	T 3/8" T.P.COMP.x1/4"NPTx3/8" T.P.COMP.	1
21	104-0060	TUBE 3/8"ODx1/4"D(POLY.) x mm LG.	1
22	104-0060	TUBE 3/8"ODx1/4"D(POLY.) x mm LG.	2
23	105-0200	COLLARS 3/8"Ø	3




450A

MACHINE	450A	INCH TOLERANCES FRACTIONS 0 ± .015 1/16 ± .005 1/8 ± .005 3/16 ± .005 1/2 ± .005 3/4 ± .005 1 ± .005 1 1/2 ± .005 2 ± .005 3 ± .005 4 ± .005 5 ± .005 6 ± .005 8 ± .005 10 ± .005 12 ± .005 14 ± .005 16 ± .005 18 ± .005 20 ± .005 24 ± .005 30 ± .005 36 ± .005 48 ± .005 60 ± .005 72 ± .005 96 ± .005 120 ± .005 144 ± .005 168 ± .005 192 ± .005 216 ± .005 240 ± .005 288 ± .005 360 ± .005 480 ± .005 600 ± .005 720 ± .005 840 ± .005 960 ± .005 1080 ± .005 1200 ± .005 1440 ± .005 1680 ± .005 1920 ± .005 2160 ± .005 2400 ± .005 2880 ± .005 3600 ± .005 4800 ± .005 6000 ± .005 7200 ± .005 8400 ± .005 9600 ± .005 10800 ± .005 12000 ± .005 14400 ± .005 16800 ± .005 19200 ± .005 21600 ± .005 24000 ± .005 28800 ± .005 36000 ± .005 48000 ± .005 60000 ± .005 72000 ± .005 84000 ± .005 96000 ± .005 108000 ± .005 120000 ± .005 144000 ± .005 168000 ± .005 192000 ± .005 216000 ± .005 240000 ± .005 288000 ± .005 360000 ± .005 480000 ± .005 600000 ± .005 720000 ± .005 840000 ± .005 960000 ± .005 1080000 ± .005 1200000 ± .005 1440000 ± .005 1680000 ± .005 1920000 ± .005 2160000 ± .005 2400000 ± .005 2880000 ± .005 3600000 ± .005 4800000 ± .005 6000000 ± .005 7200000 ± .005 8400000 ± .005 9600000 ± .005 10800000 ± .005 12000000 ± .005 14400000 ± .005 16800000 ± .005 19200000 ± .005 21600000 ± .005 24000000 ± .005 28800000 ± .005 36000000 ± .005 48000000 ± .005 60000000 ± .005 72000000 ± .005 84000000 ± .005 96000000 ± .005 108000000 ± .005 120000000 ± .005 144000000 ± .005 168000000 ± .005 192000000 ± .005 216000000 ± .005 240000000 ± .005 288000000 ± .005 360000000 ± .005 480000000 ± .005 600000000 ± .005 720000000 ± .005 840000000 ± .005 960000000 ± .005 1080000000 ± .005 1200000000 ± .005 1440000000 ± .005 1680000000 ± .005 1920000000 ± .005 2160000000 ± .005 2400000000 ± .005 2880000000 ± .005 3600000000 ± .005 4800000000 ± .005 6000000000 ± .005 7200000000 ± .005 8400000000 ± .005 9600000000 ± .005 10800000000 ± .005 12000000000 ± .005 14400000000 ± .005 16800000000 ± .005 19200000000 ± .005 21600000000 ± .005 24000000000 ± .005 28800000000 ± .005 36000000000 ± .005 48000000000 ± .005 60000000000 ± .005 72000000000 ± .005 84000000000 ± .005 96000000000 ± .005 108000000000 ± .005 120000000000 ± .005 144000000000 ± .005 168000000000 ± .005 192000000000 ± .005 216000000000 ± .005 240000000000 ± .005 288000000000 ± .005 360000000000 ± .005 480000000000 ± .005 600000000000 ± .005 720000000000 ± .005 840000000000 ± .005 960000000000 ± .005 1080000000000 ± .005 1200000000000 ± .005 1440000000000 ± .005 1680000000000 ± .005 1920000000000 ± .005 2160000000000 ± .005 2400000000000 ± .005 2880000000000 ± .005 3600000000000 ± .005 4800000000000 ± .005 6000000000000 ± .005 7200000000000 ± .005 8400000000000 ± .005 9600000000000 ± .005 10800000000000 ± .005 12000000000000 ± .005 14400000000000 ± .005 16800000000000 ± .005 19200000000000 ± .005 21600000000000 ± .005 24000000000000 ± .005 28800000000000 ± .005 36000000000000 ± .005 48000000000000 ± .005 60000000000000 ± .005 72000000000000 ± .005 84000000000000 ± .005 96000000000000 ± .005 108000000000000 ± .005 120000000000000 ± .005 144000000000000 ± .005 168000000000000 ± .005 192000000000000 ± .005 216000000000000 ± .005 240000000000000 ± .005 288000000000000 ± .005 360000000000000 ± .005 480000000000000 ± .005 600000000000000 ± .005 720000000000000 ± .005 840000000000000 ± .005 960000000000000 ± .005 1080000000000000 ± .005 1200000000000000 ± .005 1440000000000000 ± .005 1680000000000000 ± .005 1920000000000000 ± .005 2160000000000000 ± .005 2400000000000000 ± .005 2880000000000000 ± .005 3600000000000000 ± .005 4800000000000000 ± .005 6000000000000000 ± .005 7200000000000000 ± .005 8400000000000000 ± .005 9600000000000000 ± .005 10800000000000000 ± .005 12000000000000000 ± .005 14400000000000000 ± .005 16800000000000000 ± .005 19200000000000000 ± .005 21600000000000000 ± .005 24000000000000000 ± .005 28800000000000000 ± .005 36000000000000000 ± .005 48000000000000000 ± .005 60000000000000000 ± .005 72000000000000000 ± .005 84000000000000000 ± .005 96000000000000000 ± .005 108000000000000000 ± .005 120000000000000000 ± .005 144000000000000000 ± .005 168000000000000000 ± .005 192000000000000000 ± .005 216000000000000000 ± .005 240000000000000000 ± .005 288000000000000000 ± .005 360000000000000000 ± .005 480000000000000000 ± .005 600000000000000000 ± .005 720000000000000000 ± .005 840000000000000000 ± .005 960000000000000000 ± .005 1080000000000000000 ± .005 1200000000000000000 ± .005 1440000000000000000 ± .005 1680000000000000000 ± .005 1920000000000000000 ± .005 2160000000000000000 ± .005 2400000000000000000 ± .005 2880000000000000000 ± .005 3600000000000000000 ± .005 4800000000000000000 ± .005 6000000000000000000 ± .005 7200000000000000000 ± .005 8400000000000000000 ± .005 9600000000000000000 ± .005 10800000000000000000 ± .005 12000000000000000000 ± .005 14400000000000000000 ± .005 16800000000000000000 ± .005 19200000000000000000 ± .005 21600000000000000000 ± .005 24000000000000000000 ± .005 28800000000000000000 ± .005 36000000000000000000 ± .005 48000000000000000000 ± .005 60000000000000000000 ± .005 72000000000000000000 ± .005 84000000000000000000 ± .005 96000000000000000000 ± .005 108000000000000000000 ± .005 120000000000000000000 ± .005 144000000000000000000 ± .005 168000000000000000000 ± .005 192000000000000000000 ± .005 216000000000000000000 ± .005 240000000000000000000 ± .005 288000000000000000000 ± .005 360000000000000000000 ± .005 480000000000000000000 ± .005 600000000000000000000 ± .005 720000000000000000000 ± .005 840000000000000000000 ± .005 960000000000000000000 ± .005 1080000000000000000000 ± .005 1200000000000000000000 ± .005 1440000000000000000000 ± .005 1680000000000000000000 ± .005 1920000000000000000000 ± .005 2160000000000000000000 ± .005 2400000000000000000000 ± .005 2880000000000000000000 ± .005 3600000000000000000000 ± .005 4800000000000000000000 ± .005 6000000000000000000000 ± .005 7200000000000000000000 ± .005 8400000000000000000000 ± .005 9600000000000000000000 ± .005 10800000000000000000000 ± .005 12000000000000000000000 ± .005 14400000000000000000000 ± .005 16800000000000000000000 ± .005 19200000000000000000000 ± .005 21600000000000000000000 ± .005 24000000000000000000000 ± .005 28800000000000000000000 ± .005 36000000000000000000000 ± .005 48000000000000000000000 ± .005 60000000000000000000000 ± .005 72000000000000000000000 ± .005 84000000000000000000000 ± .005 96000000000000000000000 ± .005 108000000000000000000000 ± .005 120000000000000000000000 ± .005 144000000000000000000000 ± .005 168000000000000000000000 ± .005 192000000000000000000000 ± .005 216000000000000000000000 ± .005 240000000000000000000000 ± .005 288000000000000000000000 ± .005 360000000000000000000000 ± .005 480000000000000000000000 ± .005 600000000000000000000000 ± .005 720000000000000000000000 ± .005 840000000000000000000000 ± .005 960000000000000000000000 ± .005 1080000000000000000000000 ± .005 1200000000000000000000000 ± .005 1440000000000000000000000 ± .005 1680000000000000000000000 ± .005 1920000000000000000000000 ± .005 2160000000000000000000000 ± .005 2400000000000000000000000 ± .005 2880000000000000000000000 ± .005 3600000000000000000000000 ± .005 4800000000000000000000000 ± .005 6000000000000000000000000 ± .005 7200000000000000000000000 ± .005 8400000000000000000000000 ± .005 9600000000000000000000000 ± .005 10800000000000000000000000 ± .005 12000000000000000000000000 ± .005 14400000000000000000000000 ± .005 16800000000000000000000000 ± .005 19200000000000000000000000 ± .005 21600000000000000000000000 ± .005 24000000000000000000000000 ± .005 28800000000000000000000000 ± .005 36000000000000000000000000 ± .005 48000000000000000000000000 ± .005 60000000000000000000000000 ± .005 72000000000000000000000000 ± .005 84000000000000000000000000 ± .005 96000000000000000000000000 ± .005 108000000000000000000000000 ± .005 120000000000000000000000000 ± .005 144000000000000000000000000 ± .005 168000000000000000000000000 ± .005 192000000000000000000000000 ± .005 216000000000000000000000000 ± .005 240000000000000000000000000 ± .005 288000000000000000000000000 ± .005 360000000000000000000000000 ± .005 480000000000000000000000000 ± .005 600000000000000000000000000 ± .005 720000000000000000000000000 ± .005 840000000000000000000000000 ± .005 960000000000000000000000000 ± .005 1080000000000000000000000000 ± .005 1200000000000000000000000000 ± .005 1440000000000000000000000000 ± .005 1680000000000000000000000000 ± .005 1920000000000000000000000000 ± .005 2160000000000000000000000000 ± .005 2400000000000000000000000000 ± .005 2880000000000000000000000000 ± .005 3600000000000000000000000000 ± .005 4800000000000000000000000000 ± .005 6000000000000000000000000000 ± .005 7200000000000000000000000000 ± .005 8400000000000000000000000000 ± .005 9600000000000000000000000000 ± .005 10800000000000000000000000000 ± .005 12000000000000000000000000000 ± .005 14400000000000000000000000000 ± .005 16800000000000000000000000000 ± .005 19200000000000000000000000000 ± .005 21600000000000000000000000000 ± .005 24000000000000000000000000000 ± .005 28800000000000000000000000000 ± .005 36000000000000000000000000000 ± .005 48000000000000000000000000000 ± .005 60000000000000000000000000000 ± .005 72000000000000000000000000000 ± .005 84000000000000000000000000000 ± .005 96000000000000000000000000000 ± .005 108000000000000000000000000000 ± .005 120000000000000000000000000000 ± .005 144000000000000000000000000000 ± .005 168000000000000000000000000000 ± .005 192000000000000000000000000000 ± .005 216000000000000000000000000000 ± .005 240000000000000000000000000000 ± .005 288000000000000000000000000000 ± .005 360000000000000000000000000000 ± .005 480000000000000000000000000000 ± .005 600000000000000000000000000000 ± .005 720000000000000000000000000000 ± .005 840000000000000000000000000000 ± .005 960000000000000000000000000000 ± .005 1080000000000000000000000000000 ± .005 1200000000000000000000000000000 ± .005 1440000000000000000000000000000 ± .005 1680000000000000000000000000000 ± .005 1920000000000000000000000000000 ± .005 2160000000000000000000000000000 ± .005 2400000000000000000000000000000 ± .005 2880000000000000000000000000000 ± .005 3600000000000000000000000000000 ± .005 4800000000000000000000000000000 ± .005 6000000000000000000000000000000 ± .005 7200000000000000000000000000000 ± .005 8400000000000000000000000000000 ± .005 9600000000000000000000000000000 ± .005 10800000000000000000000000000000 ± .005 12000000000000000000000000000000 ± .005 14400000000000000000000000000000 ± .005 16800000000000000000000000000000 ± .005 19200000000000000000000000000000 ± .005 21600000000000000000000000000000 ± .005 24000000000000000000000000000000 ± .005 28800000000000000000000000000000 ± .005 36000000000000000000000000000000 ± .005 48000000000000000000000000000000 ± .005 60000000000000000000000000000000 ± .005 72000000000000000000000000000000 ± .005 84000000000000000000000000000000 ± .005 96000000000000000000000000000000 ± .005 108000000000000000000000000000000 ± .005 120000000000000000000000000000000 ± .005 144000000000000000000000000000000 ± .005 168000000000000000000000000000000 ± .005 192000000000000000000000000000000 ± .005
---------	------	---

007-0018



NOTE: FOR GAS INJECTION
OPTION KIT INSTALLATION
SEE DRAWING #:
450A: #010-0029
550A: #010-0013



AIR REGULATOR OPTION

NOTE: SET TO A
MAXIMUM OF 45 PSI



NOTE: FOR AIR REGULATOR
OPTION KIT INSTALLATION
SEE DRAWING #:
450A: #010-
550A: #010-

ITEM	PART #	DESCRIPTION	QT.
1	106-0010	GAS VALVE	1
2	114-0260	VACUUM GAUGE	1
3	106-0070	BELLOWS VALVE	1
4	106-0030	ATMOSPHERE VALVE	1
5	114-0147	PRESSURE REGULATOR	1
6	114-0245	PRESSURE GAUGE	1
7	114-0170	PRESSURE REGULATOR SUPPORT	1

MACHINE		450A & 550A		SIPROMAC	
PART		PNEUMATIC DRAWING		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
ITEM:	ENG:	DATE 97-03-12	SCALE	QT.	1
MAT:	APP:	DATE	007-0018		
B RE-DRAWN		MODIFICATION		M.L.	
LET.		DATE		INT.	

010-0033


ITEM	PART #	DESCRIPTION	QT.
1	005-0411	REAR VIEW MACHINE ASSEMBLY	1
2	005-0339	REAR VIEW MACHINE ASSEMBLY	1
3	101-0036	STRAIGHT 1/4" MNPT x 3/8" T.P. COMP	2
4	104-0060	TUBE 3/8" OD x 1/4" ID (POLY) x mmlG.	2
5	114-0147	PR. REG. 0-60 PSI 1/4" NPT	1
6	114-0245	PR. GAUGE 0-60 PSI 1/8" NPT	1
7	114-0170	PRESSURE REGULATOR SUPPORT	1
8	051-0144	SCREW 10-24 x 1/2" PAN PHIL SS	2
9	051-0730	WASHER #10 FLAT S/S	2
10	051-0572	NUT #10-24 NYLON LOCK SS	2
11	101-0200	STRAIGHT 1/4" MNPT x 1/4" HOSE BARB	2





-AIR REGULATOR OPTION-

MACHINE		450A & 550A		SIPROMAC	
PART		AIR REGULATOR OPTION KIT INSTALLATION		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
ITEM:		CNC:		SCALE M-E QT. 1	
MAT:		DATE 97-10-07		NO. 010-0033	
BY		DATE 05-06-20			
APP.					
MODIFICATION		DATE		INT.	
B	051-0144 WAS 051-0100, 051-0572 WAS 051-0560	05-05-05		M.A.L.	
A	051-0100 WAS 051-0147, 051-0560 WAS 051-0572	05-03-23		M.A.L.	
LET.					


VACUUM PACKAGING MACHINES




250



350/350D



450A



550A