

TRAULSEN TECHNICAL BULLETIN

PRODUCT SERVICE DEPARTMENT

FORT WORTH, TX 76137

INTELA-TRAUL ALARMS AND MEANINGS

Introduction: This technical bulletin is to inform the field of the possible Intela-Traul alarms and their meanings.

<u>Alarm</u>	<u>Meaning</u>	<u>Alarm</u>	<u>Meaning</u>
CAL SER	System leak alarm	d IS Snr	Discharge line sensor open or shorted
LO CAB	High cabinet temperature alarm	dEF Err	Defrost terminates by time not by temperature for 72 hours.
H I CAB	Low cabinet temperature alarm	Sn 1	Cab sensor open or shorted
dor OPn	Door open alarm	Sn2	Coil sensor open or shorted
ELE LOS	Power loss alarm	Sn3	Liquid line sensor open or shorted
CLnFIL	Clean condenser alarm	cH 1	High cabinet temperature alarm
CoL Snr	Coil sensor open or shorted	cLO	Low cabinet temperature alarm
CAB Snr	Cab sensor open or shorted		

Contact Traulsen Technical Service:

If further assistance is needed feel free to contact Traulsen Technical Service at 800-825-8220 between the hours of 7:30am – 11:30am CST & 12:30pm – 4:30pm CST.